

Ritron Model(s):	DMR callbox Daughtercard RQXD-DMR-U
Current Firmware Revision:	9S110407
Revision Update:	02/21/2020

DMR callbox daughtercard RQXD-DMR-U firmware revision history:

9S110407 **released: 02/21/2020**

Fixes garbling on Tx while end of Rx by initialize the circular buffer (once) on every data update to keep VCH packets received in the same order when sent to the AMBRE vocoder chip.

More stable DMR reception over a wider frequency range is implemented.

9S110406 **released: 12/14/2017**

Initial release.