

Ritron Model(s):	JBS 7-Series Base Radio
Current Firmware Revision:	9s1N5202.s19
Revision Update:	May 15, 2025

JBS 7-Series Base Radio firmware revision history:

1. **9S1N5201** **released: 04/19/2023**
 - a. Release firmware 9s1N5201.
 - b. Due to availability issues, the JBS 7-Series Base Radio is updated to replace Kinetis µP (314C0018/19) with Infineon CY8C6144LQI µP (314Q0130). Firmware 9s1N5201 is required for the Infineon CY8C6144LQI uP.
 - c. JBS 7-Series Base Radios with the Infineon CY8C6144LQI µP and 9s1N5201 firmware are identified as REV 2 on the FCC serial label.
 2. **9S1N5202** **released: 05/15/2025**
 - a. REV 2 JBS 7-Series Base Radios (Infineon uP) had a problem with DTMF encode where is does not necessarily send the programmed DTMF string correctly. Firmware revision 9S1N5202 fixes this problem.
-