

Ritron Model(s):	NXDN callbox RQX-117/417NX mainboard
Current Firmware Revision:	9S1N4109
Revision Update:	11/21/2023

RQX-117/417NX mainboard firmware revision history:

9S1N4109 released: 11/21/2023

9S1N4109 firmware fixes a problem where the NXDN Callbox was missing a PTT detection at power on.
